

原水測定記録

平成23年8月

【参考値】

月	日	曜日	東コルゲート				西コルゲート				旧東排水管				西U型側溝まわり				調整池			降水量 (mm)
			流入量		電気伝導率	水温	流入量		電気伝導率	水温	流入量		電気伝導率	水温	流入量		電気伝導率	水温		電気伝導率	水温	
			(l/min)	(PH)	(ms/m)	(°C)	(l/min)	(PH)	(ms/m)	(°C)	(l/min)	(PH)	(ms/m)	(°C)	(l/min)	(PH)	(ms/m)	(°C)	(PH)	(ms/m)	(°C)	
8	1	月	130.0	4.8	80	16.8	26.7	6.2	75	17.3	0.0	6.2	31	17.8	31.7	5.4	100	17.5	6.1	41	21.9	0.5
	2	火	126.7	4.8	84	16.5	20.0	6.1	78	17.1	0.0	6.0	31	17.7	30.0	5.5	103	17.5	6.1	50	21.7	1.5
	3	水	121.7	4.8	84	16.9	18.3	6.1	83	18.0	0.0	6.0	29	19.2	30.0	5.5	106	17.7	6.1	80	21.3	4
	4	木	118.3	4.8	83	17.2	20.0	6.2	80	17.9	0.0	6.1	28	17.7	30.0	5.5	109	17.0	6.3	74	22.0	0
	5	金	111.7	4.8	84	16.9	16.7	6.2	82	7.8	0.0	6.3	29	17.7	26.7	5.5	111	16.7	6.2	79	22.3	0
	6	土	105.0	4.9	82	17.0	15.0	6.1	83	18.1	0.0	5.7	29	22.2	25.0	5.5	112	17.3	6.1	82	22.9	0.5
	7	日	100.0	4.9	81	17.1	13.3	6.2	83	18.9	0.0	5.9	29	25.5	21.7	5.5	113	17.3	6.3	84	23.2	0
	8	月	95.0	4.9	80	17.0	11.7	6.2	82	18.5	0.0	5.6	31	18.0	21.7	5.5	112	17.3	6.3	85	23.4	0
	9	火	90.0	4.9	-	17.1	11.7	6.2	82	18.6	0.0	5.8	32	24.7	20.0	5.5	111	17.5	6.3	82	23.5	0
	10	水	86.7	4.9	-	17.2	10.0	6.2	82	19.2	0.0	6.0	32	27.0	20.0	5.5	110	17.3	6.3	84	24.3	0
	11	木	83.3	4.9	76	17.7	10.0	6.2	84	19.1	0.0	6.1	33	27.3	18.3	5.5	108	16.8	6.3	88	24.6	0
	12	金	80.0	5.0	73	17.6	8.3	6.2	83	18.8	0.0	5.7	36	20.3	18.3	5.6	107	17.2	6.1	87	23.6	0
	13	土	76.7	5.0	73	17.7	8.3	6.3	84	19.3	0.0	5.9	37	24.0	18.3	5.6	106	17.1	6.1	87	24.1	0
	14	日	75.0	5.0	75	17.4	8.3	6.2	83	18.9	0.0	6.0	36	24.1	16.7	5.7	106	17.3	6.1	86	24.3	0
	15	月	76.7	5.1	71	17.7	13.3	6.3	84	19.4	0.0	6.2	38	25.9	16.7	5.6	101	17.3	6.2	88	24.6	33.5
	16	火	78.3	5.2	67	17.5	10.0	6.3	80	18.3	0.0	6.3	36	24.3	16.7	5.6	100	17.4	6.1	73	24.4	2
	17	水	75.0	5.2	66	17.6	8.3	6.3	81	18.7	0.0	5.7	41	23.0	16.7	5.6	100	17.6	6.1	84	24.4	6.5
	18	木	71.7	5.2	66	17.7	8.3	6.4	79	19.2	0.0	5.8	41	24.4	16.7	5.6	98	17.9	6.1	83	24.4	5.5
	19	金	73.3	5.2	64	17.6	10.0	6.3	59	19.9	0.0	6.1	40	25.2	15.0	5.6	98	25.2	6.2	81	24.5	9.5
	20	土	75.0	5.3	63	17.4	10.0	6.4	78	18.0	0.0	5.8	40	24.1	16.7	5.6	97	17.3	6.2	80	23.4	13.5
	21	日	105.0	5.5	54	17.3	25.0	6.3	71	17.7	1.7	5.9	42	18.2	21.7	5.6	85	16.9	6.1	77	23.1	29
	22	月	111.7	5.4	56	17.4	30.0	6.5	61	17.3	1.7	6.2	37	18.9	28.3	6.5	61	17.3	6.2	74	22.4	7.5
	23	火	188.3	5.4	60	17.5	70.0	6.3	58	17.3	5.0	6.3	29	18.4	53.3	5.5	66	16.7	6.3	45	22.6	37
	24	水	153.3	4.9	76	17.3	36.7	5.9	78	17.3	1.7	6.3	30	19.9	46.7	5.5	85	16.6	6.3	51	21.3	0
	25	木	135.0	4.8	91	17.4	25.0	6.1	78	17.4	0.0	6.3	30	22.7	38.3	5.5	98	16.5	6.1	54	22.0	1
	26	金	120.0	4.7	95	17.0	18.3	6.0	79	18.0	0.0	6.0	27	20.1	30.0	5.5	107	16.7	6.1	60	21.5	0.5
	27	土	110.0	4.8	92	17.7	16.7	6.2	79	18.1	0.0	6.2	27	24.2	28.3	5.5	109	16.7	6.2	61	22.0	10.5
	28	日	111.7	4.8	86	17.7	18.3	6.2	76	18.3	0.0	5.8	28	18.4	26.7	5.6	108	17.1	6.2	68	22.5	7.0
	29	月	105.0	4.8	84	17.4	15.0	6.2	77	18.1	0.0	6.0	28	23.6	25.0	5.5	108	17.1	6.1	78	22.0	0.0
	30	火	100.0	4.9	79	18.3	13.3	6.2	85	17.7	0.0	6.2	30	24.6	23.3	5.2	108	17.2	6.1	80	22.3	0.0
	31	水	95.0	4.8	84	17.8	11.7	6.3	80	18.4	0.0	5.8	29	23.6	20.0	5.5	109	17.4	6.2	84	23.6	0.0

※測定時間は毎日午前9時(ただし、流入量は日平均値)
 ※現地計測による計測結果のため参考値
 ※東コルゲートの電気伝導率については、機械故障のため9日及び10日のデータ欠損